

→ Mae Willkom
Eau Claire

GWURR Package Cover Sheet

Site Name Haviland Mint Farm

Site Address 7168 Isherwood Rd

BRRTS # 03-50-001180 Date of Closure Decision 4/28/99

Parcel I.D./Tax Parcel # 010-22-0826-13

☒ Groundwater Use Restriction

☒ Location map

☒ Detailed site map

☒ Groundwater flow/isoconcentration maps

☒ Geologic cross sections

☒ Latest table(s) of analytical results (soil results included only if soil deed restriction is incorporated into groundwater use restriction document)

☒ Closure letter(s)

RECEIVED
JAN 29 2001
DNR-WL

558939.3750000 X
431684.2187500 Y

Document Number

557337

GROUNDWATER USE RESTRICTION

Recording Area

Declaration of Restrictions

In Re: Part of the NE 1/4, SE 1/4, Section 26, Township 22N, Range 8E,
Town of Buena Vista, Portage County, Wisconsin.

Real Estate Key Parcel No.: 010-22-0826-13

This groundwater use restriction applies to the area shown on Exhibit 1
which encompasses approximately 1.6 acres.

STATE OF WISCONSIN)
) ss
COUNTY OF Portage)

WHEREAS, Ardis M. Haviland Survivor's Trust is the owner of the above-
described property; and

WHEREAS, one or more gasoline or diesel fuel discharges have occurred on this
property. Benzene-contaminated groundwater above NR 140 enforcement
standards exists on this property at the location shown on Exhibit 1 at MW-21, a
monitoring well formerly located on the western side of the northernmost shed on the property. The contaminated area
encompasses and area of approximately 200 square feet, as illustrated by the shaded region on Exhibit 1. Benzene exists in
this area at a concentration of 20 parts per billion, slightly above the NR 140 enforcement standard of 5 parts per billion. The
concentration of benzene has steadily decreased in this area over four quarters of monitoring and is expected to continue to
naturally attenuate over time. An area of residual soil contamination as diesel range organics also exists along and beneath
a small portion of the western wall of the northernmost shed (shaded area on Exhibit 1), and is required to be removed if it
should become accessible. The area of soil contamination is not greater than the area of groundwater contamination; and

WHEREAS, it is the desire and intention of the property owner to impose on the Restricted Area shown on Exhibit 1
restrictions which will make it unnecessary to conduct additional soil or groundwater remediation activities on the property at
the present time.

WHEREAS, natural attenuation has been approved by the Department of Natural Resources to remediate groundwater
exceeding Chapter NR 140 groundwater standards within the boundaries of this Restricted Area; and

WHEREAS, construction of potable wells where the water quality exceeds the drinking water standards in Chapter NR 809
is restricted by Chapters NR 811 and NR 812. Special well construction standards or water treatment requirements, or both,
or well construction prohibitions may apply.

NOW THEREFORE, the owner hereby declares that the Restricted Area described above is held and shall be held, conveyed
or encumbered, leased, rented, used, occupied and improved subject to the following limitation and restriction:

Anyone who proposes to construct or reconstruct a well in the Restricted Area is required to contact the Department
of Natural Resources' Bureau of Drinking Water and Groundwater, or its successor agency, to determine what
specific prohibitions or requirements are applicable prior to constructing or reconstructing a well on this property.
No well may be constructed or reconstructed on this property unless applicable requirements are met.

REGISTER'S OFFICE
PORTAGE COUNTY, WI
RECEIVED FOR RECORD } 38

MAR 29 1999

TIME: 11:00 A.M.

Stacie A. Wisinski Senior Deputy
CYNTHIA A. WISINSKI REGISTER OF DEEDS

pd #14-

Return to:

Ardis M. Haviland
7168 Isherwood Road
Bancroft, Wisconsin 54921

010-22-0826-13

Parcel Identification Number (PIN)

This restriction is hereby declared to be a covenant running with the land and shall be fully binding upon all persons acquiring the above-described property whether by descent, devise, purchase, or otherwise. This restriction benefits and is enforceable by, the Wisconsin Department of Natural Resources, its successors and assigns. The Department, its successors or assigns, may initiate proceedings at law or in equity against any person or persons who violate or are proposing to violate this covenant, to prevent the proposed violation or to recover damages for such violation.

Any person who is or becomes owner of the Restricted Area described above may request that the Wisconsin Department of Natural Resources or its successor issue a determination that the restrictions set forth in this instrument are no longer required. Upon receipt of such a request, the Wisconsin Department of Natural Resources shall determine whether or not the restrictions contained herein can be extinguished. If the Department determines that the restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be recorded to give notice that this groundwater use restriction is no longer binding.

IN WITNESS WHEREOF, the owner of the property has executed this Declaration of Restrictions, this 16th day of March, 19 99.


Ardis M. Haviland Survivor's Trust

Signature: Ardis M. Haviland

Printed Name: Ardis M. Haviland - Trustee


Subscribed and sworn to before me
this 16th day of March, 1999.

Rick A. Fluga
Notary Public, State of WI
My commission is permanent



This document was drafted by the Wisconsin Department of Natural Resources.

FILENAME: Z:\inst\mgwrest.doc



PLOVER TROPHY



— Medals, Ribbons, Plaques —
Quality Computerized Engraving
Award Your Team With a Better Price
GET YOUR LEAGUE TROPHIES NOW!

Phone Us! 345-9898
1708 Plover Road - Plover - Highway B



GREEN ROHM
ARCHITECTS ENGINEERS

Planning, Design and Construction Services for:

Swimming Pools Parks Water Supply Systems
Athletic Facilities Highways Sewerage Systems

908 Post Road, #400, Plover, Wisconsin 54467
(715) 341-4363, Fax: (715) 341-1856


DRAWING NO. 94.380L9
 DRAWN BY: RRT
 CHECKED BY: VUL
 APPROVED BY: 329 7/6/98

MW-11
 (1,063.02)


LEGEND

- ⊕ POTABLE WELL
- ⊕ MONITORING WELL
- ⊗ SOIL SAMPLE LOCATION FROM LANDSPREAD AREA OBTAINED FROM DEPTH OF 4 INCHES.
- 1064.00 ISOELEVATION CONTOUR
- LIMIT OF REMEDIAL EXCAVATION AREA
- LIMIT OF LANDSPREAD AREA

NOTES:
 LANDSPREAD SOIL IS 4 INCHES THICK, TILLED UNDER, AND SEEDED WITHIN 72 HOURS OF SPREADING.
 • SAMPLE TAKEN ON 8/21/97




MW-1
 (1,064.63)



MW-2
 (1,065.05)

MW-4
 (1,065.00)

1065.00



Potentiometric Surface
(5/20/98)
Haviland Mint Farm Site
Bancroft, Wisconsin

FIGURE NO.

9

THE INTERPRETATIONS IN THIS FIGURE ARE BASED ON KNOWN POINTS IN TIME AND SPACE AND ARE INTEGRAL TO A WRITTEN REPORT AND SHOULD BE REVIEWED IN THAT CONTEXT.

DRAWING NO. 94.380LB
 DRAWN BY: RRT
 6/29/98
 CHECKED BY: JJA
 7/6/98
 APPROVED BY: DAI
 12/6/98

MW-11
 (<0.13)

MW-1
 (0.35)

MW-2
 (<0.13)

MW-6/
 MW-22
 (<0.13)

MW-5/MW-21
 (20)

MW-3
 (<0.13)



MW-4
 (<0.13)

LEGEND


- ⊙ POTABLE WELL
- ⊕ MONITORING WELL
- ⊗ SOIL SAMPLE LOCATION FROM LANDSPREAD AREA OBTAINED FROM DEPTH OF 4 INCHES.
- NR140 BENZENE ENFORCEMENT STANDARD ISOCONTOUR
- LIMIT OF REMEDIAL EXCAVATION AREA
- LIMIT OF LANDSPREAD AREA

NOTES: LANDSPREAD SOIL IS 4 INCHES THICK, TILLED UNDER, AND SEEDED WITHIN 72 HOURS OF SPREADING.

- SAMPLE TAKEN ON 8/21/97



Fluid Management
 A Division of ENVIROGEN, Inc.





**Groundwater Benzene
 Distribution (5/20/98)
 Haviland Mint Farm Site
 Bancroft, Wisconsin**

FIGURE NO.
8

THE INTERPRETATIONS IN THIS FIGURE ARE BASED ON KNOWN POINTS IN TIME AND SPACE AND ARE INTEGRAL TO A WRITTEN REPORT AND SHOULD BE REVIEWED IN THAT CONTEXT.

DRAWING NO. 94.380L5
 DRAWN BY: RRT
 CHECKED BY: VIL
 APPROVED BY: 8/16/98
 6/29/98




VERTICAL EXAGGERATION = 5X

LEGEND

- SOIL SAMPLE INTERVAL
- SCREENED INTERVAL
- GROUNDWATER TABLE (9/21/95)
- MSL MEAN SEA LEVEL
- (NA) NOT ANALYZED
- UST UNDERGROUND STORAGE TANK
- () CONCENTRATIONS IN ppm
- NR720 SOIL CLEANUP STANDARD ISOCONTOUR

NOTE GEOPROBES GP-3, GP-4, GP-9 AND GP-11 WERE SAMPLED 7/13-14/95
 MONITORING WELLS MW-1, MW-5 AND MW-6 AND PIEZOMETER PZ-1 WERE SAMPLED 9/5-6/95



Soil DRO Distribution
Cross-Section A-A'
Haviland Mint Farm Site
Bancroft, Wisconsin

FIGURE NO.

5

THE INTERPRETATIONS IN THIS FIGURE ARE BASED ON KNOWN POINTS IN TIME AND SPACE AND ARE INTENDED TO A WHOLE REPORT AND SHOULD BE REVIEWED IN THAT CONTEXT.

DRAWING NO.	94.380L2	DRAWN BY:	RRT	6/29/98	CHECKED BY:	VLL	7/14/98	APPROVED BY:	QAD
-------------	----------	-----------	-----	---------	-------------	-----	---------	--------------	-----

MW-11

LEGEND

- ⊙ POTABLE WELL
- ⊕ MONITORING WELL
- ⊕ PIEZOMETER
- GEOPROBE BORING

MW-1

GP-13

GP-4

GP-3

PZ-1

GP-5

FORMER UST CAVITY

GP-1

GP-7

FORMER AST

GP-14

MW-4/
GP-2

GP-5/MW-21

GP-8

GP-9

GP-10

GP-11

MW-3

FORMER AST

FORMER UST CAVITIES

SHED

SHED

SHED

WAREHOUSE

SHED

SHED

SHED


SHED

SHED

SHED

SHED

SHED



**Geoprobe Boring/Monitoring
Well Locations
Haviland Mint Farm Site
Bancroft, Wisconsin**

FIGURE NO.

2

THE INTERPRETATIONS IN THIS FIGURE ARE BASED ON KNOWN POINTS IN TIME AND SPACE AND ARE INTEGRAL TO A WRITTEN REPORT AND SHOULD BE REVIEWED IN THAT CONTEXT.


Table 3


**Preremedial Groundwater Analytical Results
Haviland Mint Farm Site
Bancroft, Wisconsin**

Sample Location	Sample Date	Benzene	Ethyl-benzene	Toluene	Xylenes	1,2,4-TMB	1,3,5-TMB	Napth-alene	GRO	DRO (ppm)	Lead (ppm)
MW-1	9/6/95	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	<1.0	<50	<0.1	0.0025
	5/28/96	220	<1.0	1.8	8.0	<1.0	<1.0	NA	330	0.26	<0.0015
	12/4/96	71	<1.0	<1.0	<3.0	<1.0	<1.0	NA	74	<0.1	NA
MW-2	9/6/95	<0.50	<1.0	<1.0	<3.0	<1.0	<1.0	<1.0	<50	<0.1	<0.0015
	5/28/96	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	NA	<50	<0.1	<0.0015
	12/4/96	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	NA	<50	<0.1	NA
MW-3	9/6/95	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	<1.0	430	2.1	<0.0015
	5/28/96	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	NA	650	<0.1	<0.0015
	12/4/96	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	NA	650	<0.1	NA
MW-4	9/6/95	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	<1.0	<50	<0.1	<0.0015
	5/28/96	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	NA	<50	0.11	<0.0015
	12/4/96	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	NA	<50	<0.1	<0.0015
MW-5	9/6/95	260	64	16	47	40	4.4	59	710	0.61	<0.0015
	5/28/96	640	280	520	1,300	250	55	NA	4,100	1.3	<0.0015
	12/4/96	400	120	68	400	40	6.4	NA	1,200	0.44	NA
MW-6	9/6/95	240	86	470	230	75	27	<20	2,900	1.6	<0.0015
	5/28/96	200	94	170	330	50	17	NA	1,100	1.1	<0.0015
	12/4/96	25	7.5	9.4	33	5.4	1.8	NA	110	0.45	NA
MW-11	12/12/96	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	NA	<50	<0.1	NA
PZ-1	9/6/95	0.78	<1.0	<1.0	<3.0	<1.0	<1.0	<1.0	<50	<0.1	<0.0015
	5/28/96	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	<1.0	<50	<0.1	<0.0015
	12/4/96	<0.5	<1.0	<1.0	<3.0	<1.0	<1.0	NA	<50	<0.1	NA
NR 140 ES		5.0	700	343	620	NS	NS	40	NS	NS	0.015
NR 140 PAL		0.5	140	68.6	124	NS	NS	8	NS	NS	0.0015

Notes:

All results are reported in ppb unless otherwise noted

 Shading indicates value equals or exceeds the NR 140 enforcement standard

 Cross hatching indicates value equals or exceeds the NR 140 preventive action limit

TMB: Trimethylbenzene
GRO: Gasoline range organics
NA: Not analyzed
NS: No standard

ES: Enforcement standard
PAL: Preventive action limit
DRO: Diesel range organics

Checked by: VUApproved by: Gy

Table 5

**Post Remedial Groundwater Laboratory Analytical Results
Haviland Mint Farm
Bancroft, Wisconsin**

Well Location	Sample Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	1,2,4-TMB	1,3,5-TMB	Naphthalene	GRO	DRO (ppm)
MW-1	8/21/97	85	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	90	0.62
	11/24/97	16	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	<50	0.21
	2/12/98	0.48	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	<50	0.35
	5/20/98	0.35	<0.22	<0.20	<0.23	<0.20	<0.22	<0.29	NA	<50	0.50
MW-2	8/21/97	<0.13	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	<50	0.29
	11/24/97	<0.23	<0.22	<0.20	<0.23	<0.16	0.4	<0.29	NA	<50	<0.10
	2/12/98	<0.13	<0.22	<0.20	<0.23	<3.4	<0.22	<0.29	NA	<50	<0.10
	5/20/98	<0.13	<0.22	<0.20	<0.23	<0.20	<0.22	<0.29	NA	<50	0.11
MW-3	8/21/97	<0.13	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	<50	0.31
	11/24/97	<0.13	<0.22	<0.20	<0.23	<0.16	0.22	<0.29	NA	<50	<0.10
	2/12/98	<0.13	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	<50	0.21
	5/20/98	<0.13	<0.22	<0.20	<0.23	<0.20	<0.22	<0.29	NA	<50	0.19
MW-4	8/21/97	<0.13	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	<50	0.2
	11/24/97	<0.13	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	<50	<0.10
	2/12/98	<0.13	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	<50	0.2
	5/20/98	<0.13	<0.22	<0.20	<0.23	<0.20	<0.22	<0.29	NA	<50	0.13
NR 140 ES		5	700	343	620	40	NS	NS	40	NS	NS
NR 140 PAL		0.5	140	68.6	124	8	NS	NS	8	NS	NS

(Continued)

Notes:

All results are reported in ppb unless otherwise noted

Shading indicates value equals or exceeds the NR 140 enforcement standard

MTBE: Methyl t-butyl ether DRO: Diesel range organics

TMB: Trimethylbenzene NA: Not analyzed

GRO: Gasoline range organics NS: No standard

Checked by: VU Approved by: Guy

Table 5 (Continued)
Post Remedial Groundwater Laboratory Analytical Results
Haviland Mint Farm
Bancroft, Wisconsin

Well Location	Sample Date	Benzene	Ethylbenzene	Toluene	Xylenes	MTBE	1,2,4-TMB	1,3,5-TMB	Naphthalene	GRO	DRO (ppm)
MW-11	8/21/97	<0.13	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	<50	<0.10
	11/24/97	<0.13	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	<50	<0.10
	2/12/98	<0.13	<0.22	<0.20	0.44	<1.0	<0.22	<0.29	NA	<50	<0.10
	5/20/98	<0.13	<0.22	<0.20	<0.23	<0.20	<0.22	<0.29	NA	<50	<0.10
MW-21	8/21/97	190		0.7		<0.32	110	4.6	<1.0	1,200	1.1
	11/24/97	150	50	0.44	15	<0.16	7.4	<0.29	NA	400	0.29
	2/12/98	120	38	0.76	6.1	<0.16	5	<0.29	NA	340	0.85
	5/20/98	20	19	<0.20	12	<0.60	8.3	<0.29	NA	140	0.39
MW-22	8/21/97		<0.22	<0.20	<0.23	<0.16	0.22	<0.29	<1.0	<50	1
	11/24/97	<0.13	<0.22	<0.20	<0.23	<0.16	<0.22	<0.29	NA	<50	0.27
	2/12/98	<0.13	<0.22	<0.20	0.43	<0.16	0.27	<0.29	NA	<50	0.65
	5/20/98	<0.13	<0.22	<0.20	<0.23	<30	<0.22	<0.29	NA	<50	1.0
NR 140 ES		5	700	343	620	40	NS	NS	40	NS	NS
NR 140 PAL		0.5	140	68.6	124	8	NS	NS	3	NS	NS

Notes:

All results are reported in ppb unless otherwise noted

Shading indicates value equals or exceeds the NR 140 enforcement standard

Cross hatching indicates value equals or exceeds the NR 140 preventive action limit

MTBE: Methyl t-butyl ether

DRO: Diesel range organics


TMB: Trimethylbenzene

NA: Not analyzed

GRO: Gasoline range organics

NS: No standard

Checked by: VU Approved by: ewj



State of Wisconsin \ DEPARTMENT OF NATURAL RESOURCES

Tommy G. Thompson, Governor
George E. Meyer, Secretary
Scott Humrickhouse, Regional Director

Wausau Office
5301 Rib Mountain Drive
Wausau, WI 54401
TELEPHONE 715-359-4522
FAX 715-355-5253

October 30, 1998

BRRTS: 03-50-001180

Ms. Ardis Haviland
7168 Isherwood Road
Bancroft, WI 54921

FILE COPY

SUBJECT: Case Closure
Haviland Mint Farm
7168 Isherwood Road, Bancroft, WI

Dear Ms. Haviland:

On October 14, 1994, the Department of Natural Resources provided a notice to you that the degree and extent of petroleum contamination at the above-named site was required to be investigated and remediated. We have since been informed that the required investigation and remediation has been accomplished. On October 28, 1998, the site was reviewed by the West Central Regional Close Out Committee for a determination as to whether or not the case qualified for close out under ch. NR 726, Wis. Adm. Code.

Based on the investigative and remedial documentation provided to the Department, there is soil and groundwater contamination remaining at the site. The soil contamination is above NR 720 soil standards and the groundwater contamination is above the NR 140 groundwater standards. The groundwater contaminant plume appears to be stable and there is evidence that natural attenuation is remediating the contamination. Closure under NR 726.05(2)(b), Wis. Adm. Code has been requested and the closure committee has approved this closure with the following conditions.

A groundwater use restriction which meets the requirements of NR 726.05(8)(am), Wis. Adm. Code, must be recorded with the County Register of Deeds within 30 days. Once the Department has received documentation that the restriction has been recorded and all other conditions for closure have been met, the case will be considered closed. This means that no further action is necessary on the site at this time. I have included a copy of a model groundwater use restriction for your use.

If the building that is over the existing soil contamination is removed or any other excavation or subsurface work is conducted in this area, the contaminated material will need to be treated or disposed of in accordance with applicable laws.

Also, the Department requires that the monitoring wells that were installed during the investigation and remedial activities be properly abandoned in accordance with

Administrative Code NR 141.25. Documentation substantiating proper abandonment (Form 3300-5W) should be forwarded to me at the above address.

The case may be reopened pursuant to s. NR 726.05(2)(b)2-5 or NR 726.09, Wis. Adm. Code, if additional information regarding site conditions indicates that natural attenuation is no longer an effective remedial action; or if contamination on the site poses a threat to public health, safety, or welfare of the environment.

If you have additional relevant information which was not formerly provided to the Department, and which you feel would significantly impact the Department's closure decision, you may submit that information for our re-evaluation of case closure. The Department appreciates the actions you have undertaken to restore the environment. If you have any questions, please feel free to call me at (715) 359-1777.

Sincerely,

A handwritten signature in black ink, appearing to read "Michael MacDonald", written over a horizontal line.

Michael MacDonald - Hydrogeologist
Remediation and Redevelopment Program

cc: Victoria Loveland - Envirogen (FMI) - Mosinee

557337

MW-11-

SITE SURVEY

FMI JOB # 94,380, HAVILAND MINT FARM, 7168 ISHERWOOD ROAD, BANCROFT, WI. 54921. LOCATED IN SECTION 26, TOWNSHIP 22 NORTH, RANGE 8 EAST, TOWN OF BUENA VISTA, PORTAGE COUNTY, WISCONSIN.


I, DAVID L. OSTERBRINK, REGISTERED LAND SURVEYOR, HEREBY CERTIFY THAT I HAVE LOCATED ALL VISIBLE IMPROVEMENTS, DETERMINED ELEVATIONS AND COORDINATES OF WELLS. THAT I HAVE DONE THIS TO THE BEST OF MY KNOWLEDGE AND BELIEF.

DAVID L. OSTERBRINK RLS NO. S-2014
NORTHWOODS SURVEYING
823 JEFFERSON STREET
WAUSAU, WI. 54403
715-845-1249
REVISED 12-31-98 ADDED MW-11- AND BENCH MARK ELEVATIONS


MONITORING WELL INFO.

WELL #	COORDINATES		ELEVATION	
	NORTH	EAST	GROUND	PVC
MW-1-	10512.75	10078.73	1072.8	1075.30
MW-2-	10288.88	10221.52	1076.9	1079.32
MW-3-	10072.33	10113.25	1076.4	1078.18
MW-4-	10273.80	9982.27	1077.2	1079.43
MW-5-	10271.41	10081.78	1077.4	1079.51
MW-6-	10129.95	10185.30	1076.4	1078.51
PZ-1-	10273.35	10075.70	1077.5	1079.89
MW-11-	11034.72	10150.80	1075.93	1076.02

TOP OF STEEL Casing
WELL ELEVATIONS REFERENCED TO ALUMINUM DISC, NORTHWEST CORNER, SOUTH BOUND BRIDGE, USH "51" OVER DRAINAGE DITCH #3 WL DOT ELEVATION = 1075.57. COORDINATES ARE ASSUMED GRID OF 10,000, 10,000.



Scale 1" = 100 ft



Notes: MW-5 and MW-6 were replaced with MW-21 and MW-22 after the remedial excavation
Area of residual soil/groundwater contamination

Exhibit 1
Site Survey
Haviland Mint Farm Site
Bancroft, Wisconsin